ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0300, W0351, W0298

Street Name
4th Crs Lakshmi Sagar Lyt, S Krishnappa Lyt, Manjunath Floor Mill Rd

Significant Landmark
Ashraya layout Residency roads

Segment No.
11/C-W0300/S023714

Total Length (m)
322.44

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	142.63	77.537240	13.076822	77.538547	13.076678	W0351	W0027
2	179.81	77.537078	13.076548	77.538724	13.076355	W0351	W0027

Work Details

History of Road / Lane / Circles

Name of the Work
Road Development and asphalting work at Ashraya layout Residency roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Road Development and asphalting work at Ashraya layout Residency roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-15-000037

Work Order No.
EE/BTP/BBMP/E-PMT/63/2015-16

Work Order Date
29/03/2015

Period of Extention
60 Days

Defect Liability Period From
15/12/2015

Defect Liability Period To
14/12/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N KEERTHI		0.00

Phone No.	E-Mail ID
9731567144	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		RANGANATH

Date of Inspection	Remarks
18/03/2017	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	11	Ward Name:	Kuvempu Nagar	Street ID:	W0300, W0351, W0298

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	17/04/2017	COMPLETED
SE	VASU K M	19/03/2017	17/04/2017	COMPLETED
EE	YARAPPA REDDY	18/03/2017	17/04/2017	COMPLETED
AEE	MAHADEV	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0300, W0351, W0298